



Main office:: 110 Shawmut Road, Ste. 2, Canton, Massachusetts 02021 • Tel: (781) 401 - 3288 • Fax: (781) 828 - 3642

315 Cloverleaf Drive, Unit E, Baldwin Park, CA 91706 • Tel: (626) 937 - 6727 • Fax: (626) 937 - 6730

www. Tractel.com

e-mail: griphoist@tractel.com

PRODUCT NOTIFICATION

March 5, 2008

Please note that the Tractel Double Blocstop series (BS/BSO) may be operated without the use of a secondary wire rope.

In this case, it is not required to reeve the primary wire rope through the wire rope detector arm.

When using (1) rope, personal fall protection equipment must meet the requirements of a (1) wire rope system.

A handwritten signature in cursive script that reads "Cliff Theve".

Cliff Theve
Engineering Manager
Tractel GripHoist Division